

Borehole D


Monitored data for : Borehole D - Railway Arches (Down Stream East Bank)

Session	Measured depth to Ground Water (OD) cms	Well Head 23.816 (OD) mtrs	Absolute Ground level (OD) mtrs	Change in Absolute Ground level (OD) cms	Measured depth to Stream (OD) cms	Ref. - D/S Arch Under Buttress Level (OD) mtrs	Absolute Stream Water Level (OD) mtrs	Change in Absolute Stream Water Level (OD) cms	rainfall mm	change
22-Nov-07	258	23.82	21.24	0	215	23.48	21.33	0	92.2	0
11-Dec-07	266	23.82	21.16	-8	228	23.48	21.20	-13	45.6	-46.6
08-Jan-08	282	23.82	21.00	-16	232	23.48	21.16	-4	88.0	42.4
04-Feb-08	263	23.82	21.19	19	228	23.48	21.20	5	21.6	-66.4
05-Mar-08	279	23.82	21.03	-16	217	23.48	21.31	10	81.2	59.6
07-Apr-08	273	23.82	21.09	6	228	23.48	21.20	-11	47.4	-33.8
06-May-08	278	23.82	21.04	-5	227	23.48	21.21	1	69.1	21.7
09-Jun-08	258	23.82	21.24	20	230	23.48	21.18	-3	59.3	-9.8
07-Jul-08	277	23.82	21.05	-19	233	23.48	21.15	-3	64.8	5.5
07-Aug-08	288	23.82	20.94	-11	233	23.48	21.15	0	67.0	2.2
03-Sep-08	288	23.82	20.94	0	233	23.48	21.15	0	58.4	-8.6
07-Oct-08	292	23.82	20.90	-4	231	23.48	21.17	2	51.6	-6.8
05-Nov-08	297	23.82	20.85	-5	228	23.48	21.20	3	68.2	16.6
10-Dec-08	290	23.82	20.92	7	230	23.48	21.18	-2	31.7	-36.5
08-Jan-09	294	23.82	20.88	-4	234	23.48	21.14	-4	55.9	24.2
11-Feb-09	223	23.82	21.59	71	222	23.48	21.26	12	66.2	10.3
11-Mar-09	272	23.82	21.10	-49	225	23.48	21.23	-3	26.3	-39.9
08-Apr-09	285	23.82	20.97	-13	227	23.48	21.21	-2	27.0	0.7
12-May-09	294	23.82	20.88	-9	231	23.48	21.17	-4	39.2	12.2
16-Jun-09	296	23.82	20.86	-2	232	23.48	21.16	-1	31.6	-7.6
14-Jul-09	303	23.82	20.79	-7	228	23.48	21.20	4	63.2	31.6
11-Aug-09	298	23.82	20.84	5	238	23.48	21.10	-10	37.0	-26.2
10-Sep-09	309	23.82	20.73	-11	237	23.48	21.11	1	13.1	-23.9
13-Oct-09	310	23.82	20.72	-1	240	23.48	21.08	-3	43.4	30.3
10-Nov-09	307	23.82	20.75	3	249	23.48	20.99	-9	134.6	91.2
08-Dec-09	259	23.82	21.23	48	221	23.48	21.27	28	97.7	-36.9
19-Jan-10	249	23.82	21.33	10	230	23.48	21.18	-9	62.9	-34.8
10-Feb-10	266	23.82	21.16	-17	226	23.48	21.22	4		
07-Mar-10	256	23.82	21.26	10	215	23.48	21.33	11		
13-Apr-10	272	23.82	21.10	-16	217	23.48	21.31	-2		

MWRG takes no responsibility for the accuracy of the data contained on this sheet.

All topographical survey levels, rainfall figures, on-site measurements and their graphical representations must be confirmed for their accuracy by a suitably qualified professional surveyor and engineer.

Borehole D- railarches (East Bank) water level changes over time



Borehole D-railarches (East Bank) groundwater & stream levels

